

DETAIL STATUS OF THE EXISTING RIVER/SALINE EMBANKMENT

MAIN DAM DIVISION, BURLA

MAIN DAM SUB-DIVISION, HIRAKUD

NAME OF THE DIVISION

NAME OF THE SUB-DIVISION

Sl.No.	Name of the Embankment	Category of the Embankment			Length in km.	Name of the Basin	Name of the River	District.	Reach	Status of the Embankment (Reach wise)				Brief description about deficiency in parameters		
		C.E	O.A.E	T.R.E						S.E	TBL "m"	Side slope	Top width "m"		Revetment Packing "m" with location	Spur in nos. with location
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17
MAIN DAM SUB DIVISION, HIRAKUD																
1	Left flood embankment of river Mahanadi in downstream of Hirakud Dam Project		O.A.E			1.80	Lower Mahanadi Basin	Mahanadi	Sambalpur	.....	161.25	1:2.0	3.60	1800	nil	Embankment in sound and good condition.

*Sg*  
22/10/18  
ASSISTANT ENGINEER  
Store Section, Hirakud

*Rishu*  
DEPUTY EXECUTIVE ENGINEER  
MAIN DAM SUB DIVISION, HIRAKUD

*22/10/18*  
EXECUTIVE ENGINEER  
MAIN DAM DIVISION, BURLA

*[Signature]*  
SUPERINTENDING ENGINEER  
HIRAKUD DAM CIRCLE, BURLA

*[Signature]*  
DISTRICT MAGISTRATE & COLLECTOR  
SAMBALPUR