

SUNDARGARH IRRIGATION DIVISION, SUNDARGARH

NAME OF THE SUB-DIVISION:- SUNDARGARH IRRIGATION SUB-DIVISION

Sl. No.	Name of the Embankment	Category of the Embankment				Length in Km.	Name of the Basin	Name of the River	District	Reach	Status of the Embankment (Reach wise)						Brief description about deficiency in parameters
		C.E.	O.A.E	T.R.E	S.E.						TBL "m"	Side slope	Top width "m"	Revertment "m" with location	Spur in location	17	
1	FPE on right bank of river Ichha near village Suruguda. RD 00 to 345 mtr. Lat- 22.1052/InG-83.8431	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	No deficiency detected till date
2	FPE on right bank of river Ichha near Tahasil office of Lephripara. RD 00 to 300 mtr. Lat-22.1180/InG-83.8056			TRE		0.300	Mahanadi	Ichha	Sundargarh		253.700	1.5:1	1.50			No deficiency detected till date	
3	FPE on right bank of river Ichha near village Chhatenpali. RD 00 to 176 mtr. Lat-22.0938/InG-83.8803			TRE		0.176	Mahanadi	Ichha	Sundargarh		232.800	1.5:1	2.80	46.00		No deficiency detected till date	
4	FPE on left bank of river Ichha near village Jhariapali. RD 00 to 120 mtr. Lat- 22.0832/InG-83.8858			TRE		0.120	Mahanadi	Ichha	Sundargarh		229.280	1.5:1	2.70			No deficiency detected till date	

certified that inspected 100% of the embankment as listed above.

[Signature]
21.4.18
Asst. Engineer

certified that inspected 100% of the embankment as listed above

[Signature]
21/4/18

inspected 60% of the above embankment during the month 4/18.

[Signature]
21.4.18
Executive Engineer
Sundargarh Irr. Divn
Sundargarh

Deputy Executive Engineer
Sundargarh Irrigation Sub-Division
Sundargarh

[Signature]

COLLECTOR
SUNDARGARH

Inspected above

embankments & found safe

[Signature]
21/4/18
Superintending Engineer
Sundargarh Irrigation Circle
Sundargarh