

**PRE-FLOOD RIVER EMBANKMENT STATUS INSPECTION REPORT FOR THE YEAR 2016-17**

**SUNDARGARH IRRIGATION DIVISION, SUNDARGARH.**

**NAME OF THE SUB-DIVISION:-SUNDARGARH IRRIGATION SUB-DIVISION.**

Sl No.	Name of the Embankment	Category of the Embankment				Length in km.	Name of the Basin.	Name of the River.	District	Reach	Status of the Embankment(Reach wise)					Brief description about deficiency in parameters
		C.E.	O.A.E	T.R.E.	S.E.						TBL "m"	Side slope	Top width "m"	Revetment packing in "m" with location.	Spur in Nos. with location	
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17
1	FPE on right bank of river Ichha near village Suruguda.			TRE		0.345	Mahanadi	Ichha	Sundargarh		241.650	1.5:1	2.50			No deficiency.
2	FPE on right bank of river Ichha near Tahasil office of Lephripara.			TRE		0.300	Mahanadi	Ichha	Sundargarh		253.700	1.5:1	1.50			No deficiency.
3	FPE on right bank of river Ichha near village Chhatenpali.			TRE		0.176	Mahanadi	Ichha	Sundargarh		232.800	1.5:1	2.80	46.00		No deficiency.
4	FPE on left bank of river Ichha near village Jhariapali.			TRE		0.120	Mahanadi	Ichha	Sundargarh		229.280	1.5:1	2.70			No deficiency.

Certified that I have inspected 100% of the embankment in Sl. No. 1 & 2 on 24.4.2016  
*(Signature)*  
 28/4/16  
 A.E. Secy (R.S.I.D.)

Certified that I have inspected 100% of the embankment in Sl. No 3 & 4 on 24.4.2016  
*(Signature)*  
 28.4.16  
 A.E. Section 2

Certified that I have inspected 100% of the embankment in Sl. No 1 to 4 on dated 22.4.2016 to 24.4.16  
*(Signature)*  
 28.4.16  
 Deputy Executive Engineer  
 Sundargarh Irrigation Sub-Division  
 Sundargarh

Certified that I have inspected 80% of the above flood embankments between 22/4 to 24/4/2016.  
*(Signature)*  
 29/4/2016  
 Executive Engineer  
 Sundargarh Irrigation Division  
 Sundargarh

Inspected the flood embankment of Ichha river near Tahasil office Lephripara + Chhatenpali village + found safe  
*(Signature)*  
 Superintending Engineer  
 Sundargarh Irrigation Circle  
 Sankara, Sundargarh