

INFORMATION REGARDING EXISTING RIVER / SALINE EMBANKMENTS OF JONK IRRIGATION DIVISION, NUAPADA

Sl. No.	Basin	River	District	Block	Constituency	Left / Right	Name of the embankment	Type & Length of embankments				Remarks
								CE	OAE	TRE	Saline	
1	2	3	4	5	6	7	8	9	10	11	12	13
1	Mahanadi	Jonk	Nuapada	Nuapada	Nuapada	L/R	Patora Embankment (Embankment near village Patora D/S of spillway)		0.80			
2	Mahanadi	Silda Nallah	Nuapada	Nuapada	Nuapada	R	Silda Embankment (Embankment near village Silda)		0.20			
3	Mahanadi	Jonk	Nuapada	Nuapada	Nuapada	R	Kurumunda Embankment (Embankment over Jonk river near village Kurumunda)		0.90			
4	Mahanadi	Kharkhara Nallah	Nuapada	Nuapada	Nuapada	L/R	Kalyanpur Embankment (Embankment near village Kalyanpur & U/S of Kharkhara barrage)		0.90			
5	Mahanadi	Kharkhara Nallah	Nuapada	Nuapada	Nuapada	L	Chanabeda Embankment (Embankment near village Chanabeda in D/S of Kharkhara barrage)		0.60			
6	Mahanadi	Kharkhara Nallah	Nuapada	Nuapada	Nuapada	L/R	Mahatamtora Embankment (Embankment near village Mahatamtora of Kharkhara nallah)		0.50			
7	Mahanadi	Sundar	Nuapada	Komna	Nuapada	L/R	Ichhapur Embankment (Embankment near village Ichhapur in D/S of spillway of Sundar Irrigation Project)		2.00			
8	Mahanadi	Arjun Jharia Nallah	Nuapada	Komna	Nuapada	L/R	Thongo Embankment (Embankment near village Thongo)		0.90			
TOTAL									6.80			

I have visited the river embankments from SI.No.1 to 3 covering 100% length and there is no vulnerable points noticed.

[Signature]
18/4/18
Asst.Engineer

I have visited the river embankments from SI.No.1 to 3 covering 100% length and there is no vulnerable points noticed.

[Signature]
18.4.18
Sub-Divisional Officer,
Jonk Dam Sub-Division, Patora

I have visited the river embankments from SI.No.4 to 6 covering 100% length and there is no vulnerable points noticed.

[Signature]
18/4/2018
Asst.Engineer

I have visited the river embankments from SI.No.4 to 6 covering 100% length and there is no vulnerable points noticed.

[Signature]
18.4.18
Sub-Divisional Officer,
Kharkhara Irrign Sub-Division, Nuapada

I have visited the river embankments from SI.No.7 & 8 covering 100% length and there is no vulnerable points noticed.

[Signature]
19.04.18
Junior Engineer

I have visited the river embankments from SI.No.7 & 8 covering 100% length and there is no vulnerable points noticed.

[Signature]
18.04.2018
Sub-Divisional Officer,
Sundar Irrign Sub-Division, Jadamunda

I have visited the river embankments from SI.No.1 to 8 covering 54% length and there is no vulnerable points noticed.

[Signature]
18/4/18
Executive Engineer,
Jonk Irrigation Division, Nuapada

Counter Signed

[Signature]
5/5/2018
Superintending Engineer
Western Irrigation Circle
Bhawanipatna

Taneshwari Sekh
18/4/2018
Chairman
Panchayat Samiti, Nuapada

[Signature]
18/4/18
Collector
Nuapada
Counter Signatory