

FORMAT - I

**STATUS OF PROCUREMENT OF FLOOD FIGHTING MATERIALS FOR THE ENSUING FLOOD-2016 UNDER
NAYAGARH IRRIGATION DIVISION, NAYAGARH**

Sl.No	Description	Empty Gunny Bags(Nos)	Sand(Cum)	Bamboo (Nos.)	Bullah (Nos.)	Bamboo mat(Sqm)
A	Requirement of Flood Fighting materials for ensuing Flood 2015	77000	625	-	500	-
B	Flood Fighting materials already procured by 30.05.2016	77000	625	-	500	-
C	Location of Storage of Flood Fighting materials					
1	Kantilo Section Office	20000	100	-	100	-
2	Khandapada	10000	80	-	-	-
3	Nandabara	10000	70	-	-	-
4	Sidhamula	-	50	-	-	-
5	Gania Section Office	3000	20	-	50	-
6	Rajingi	1500	25	-	-	-
7	Chhadmul	1500	25	-	-	-
8	Sikrida	1500	30	-	-	-
9	Madhyakhanda	1000	20	-	-	-
10	Kadua	1000	20	-	-	-
11	Nayagarh Section Office	3000	-	-	-	-
12	Baunsiapada	1000	35	-	-	-
13	Sanapandusara	1000	15	-	-	-
14	Champatipur	1000	50	-	-	-
15	Sarankul Section Office	2000	20	-	-	-
16	Bilagorada	1000	15			
17	Domuhani	1000	15			



**Executive Engineer
Nayagarh Irrigation Division
Nayagarh**

FORMAT-II

STATUS OF SLUICES UNDER NAYAGARH IRRIGATION DIVISION

Sl No	Name/Loacation	River embankment left/ right	RD in km	Condition	Remarks
1	2	3	4	5	6
1	Sidhhamula - I	Mahanadi Right		Working Condition	Two Vented
2	Sidhhamula - II	Mahanadi Right		Working Condition	Two Vented
3	Ghanasalia	Mahanadi Right		Working Condition	Single Vented
4	Kumundi	Mahanadi Right		Working Condition	Single Vented
5	Gandhi Park,Kantilo	Mahanadi Right		Working Condition	Single Vented
6	Dhoba Sahi,Kantilo	Mahanadi Right		Working Condition	Single Vented
7	Manjarighai	Mahanadi Right		Working Condition	Single Vented
8	Laxmiprasad	Kamei Right		Working Condition	Single Vented
9	Dhanchengeda	Kamei Right		Working Condition	Single Vented
10	Guntuhni No-1	Lunijhara Left		Working Condition	Single Vented
11	Guntuhni No-2	Lunijhara Left		Working Condition	Single Vented
12	Chandi	Lunijhara Left		Working Condition	Single Vented
13	Saluni	Lunijhara Left		Working Condition	Single Vented
14	Betakholi	Kusumi Right		Working Condition	Single Vented
15	Tikiripada	Kusumi Right		Working Condition	Single Vented
16	Puania	Kusumi Left		Working Condition	Single Vented
17	Gopinathpur	Kuanria Left		Working Condition	Single Vented
18	Fategarh	Kaligiri Left		Working Condition	Non -Gated
19	Pathardwar	Kuanria Right		Working Condition	Non -Gated
20	Sundari Nalla	Kuanria Right		Working Condition	Single Vented
21	Sarapokhari	Kuanria Left		Working Condition	Single Vented
22	Jadunathpur Sasan	Kusumi Right		Working Condition	Single Vented
23	Raigadia	Brutang Left		Working Condition	Three Vented
24	Mahukana	Brutang Right		Working Condition	Single Vented
25	Krushnaprasad No-1	Kuanria Right		Working Condition	Single Vented
26	Krushnaprasad No-3	Kuanria Right		Working Condition	Single Vented
27	RD 0.345 KM	Kusumi Left	RD 0.345 KM	Working Condition	Non -Gated
28	RD 1.304 KM	Kusumi Left	RD 1.304 KM	Working Condition	Non -Gated
29	RD 2.063 KM	Kusumi Left	RD 2.063 KM	Working Condition	Non -Gated
30	RD 2.433 KM	Kusumi Left	RD 2.433 KM	Working Condition	Non -Gated
31	RD 3.562 KM	Kusumi Left	RD 3.562 KM	Working Condition	Non -Gated
32	RD 4.320 KM	Kusumi Left	RD 4.320 KM	Working Condition	Non -Gated
33	RD 1.540 KM	Kusumi Right	RD 1.540 KM	Working Condition	Non -Gated
34	RD2.115 KM	Kusumi Right	RD2.115 KM	Working Condition	Non -Gated
35	RD2.942 KM	Kusumi Right	RD2.942 KM	Working Condition	Non -Gated
36	RD 3.480 KM	Kusumi Right	RD 3.480 KM	Working Condition	Non -Gated
37	RD 4.125 KM	Kusumi Right	RD 4.125 KM	Working Condition	Non -Gated
38	RD 5.693 KM	Kusumi Right	RD 5.693 KM	Working Condition	Non -Gated
39	RD 5.870 KM	Kusumi Right	RD 5.870 KM	Working Condition	Non -Gated
40	RD 7.322 KM	Kusumi Right	RD 7.322 KM	Working Condition	Non -Gated
41	RD 8.413 KM	Kusumi Right	RD 8.413 KM	Working Condition	Non -Gated
42	Dimisara	Duanto Left		Working Condition	Two Vented

1	2	3	4	5	6
43	Fasipada	Duanto Left		Working Condition	Single Vented
44	RD 0.940 Km	Duanto Right		Working Condition	Single Vented
45	RD 1.180 KM	Duanto Right		Working Condition	Single Vented
46	Khalipatana	Duanto Right		Working Condition	Two Vented
47	Haripur	Duanto Right		Working Condition	Single Vented
48	Notar -I	Duanto Right		Working Condition	Single Vented
49	Notar -II	Duanto Left		Working Condition	Single Vented
50	Panibhandar	Duanto Right		Working Condition	Two Vented
51	Gambharidihi	Duanto Right		Working Condition	Two Vented
52	Deuli	Duanto Right		Working Condition	Two Vented
53	Tipura Nuagaon	Duanto Right		Working Condition	Single Vented
54	Tipura	Duanto Right		Working Condition	Single Vented
55	Natugaon	Duanto Left		Working Condition	Two Vented
56	Rajanagar	Mandakini Left		Working Condition	Single Vented
57	Lathipada	Sulia Left		Working Condition	Two Vented
58	Haripur	Dahuka Right		Working Condition	Two Vented
59	Balugaon	Dahuka Left		Working Condition	Single Vented
60	Kridaspur	Dahuka Left		Working Condition	Single Vented
61	Khandugaon	Dahuka Right		Working Condition	Single Vented
62	Totasahi	Dahuka Right		Working Condition	Single Vented
63	Bakalbandha	Dahuka Right		Working Condition	Single Vented
64	Dimirijhari	Dahuka Right		Working Condition	Two Vented


 Executive Engineer
 Nayagarh Irrigation Division
 Nayagarh